# Oil Field Environmental Incident Summary

**Responsible Party:** CORINTHIAN EXPLORATION (USA) CORP **Well Operator:** CORINTHIAN EXPLORATION (USA) CORP

Well Name: Skarphol CTB

Field Name: NORTH SOURIS Well File #:

Date Incident:6/9/2014Time Incident:14:00Facility ID Number:200884-01County:BOTTINEAUTwp:164Rng:77Sec:33Qtr:SW NE

Location Description: A leak was detected from a non-operational pipeline off the South East corner

of the Skarphol Central Tank Battery

Submitted By: Patrick Gratton Received By:

Contact Person: Patrick Gratton

STE 230, 323-10TH AVE SW CALGARY, AB T2R 0A5

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 5 Barrels 5 Barrels

Brine 1 Barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

## Risk Evaluation:

The area surrounding the failed pipeline is contaminated with well effluent. All contamination will be sent to a third party waste facility.

## Areal Extent:

0.5 acre

# Potential Environmental Impacts:

The environmental impact is still under review. The contaminated area will be surveyed and excavated to remove any foreign substance spilt.

#### Action Taken or Planned:

When the spill was detected near the Skarphol CTB it was unclear which pipeline was contributing to the release. All wells associated to the facility were immediately shut in and the line was exposed to determine that the inactive Moen 1 emulsion pipeline to the Skarphol CTB had corroded. The 1500 foot pipeline was leaking residual oil off the corner of the lease into the area pasture and construction crews were contacted to remove the oil saturated soil. After discussions with the prior field operator, it was determined that this non-active pipeline was originally installed in the late 1950's. Corinthian Exploration (USA) Corp. will do a full risk review of all pipelines to prevent another release of fluid.

Wastes Disposal Location: Clean Harbors Sawyer Waste Facility

Agencies Involved:

# **Updates**

Date: 6/25/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Pipeline leak from an out-of-service pipeline near the Skarphol CTB. Report states that the release impacted 1/2 acre. If that is the case, then the leak must have been quite a bit larger than 6 bbls total. Followup is necessary.

Date: 6/26/2014 Status: Inspection Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Arrived on location at 6/26/14.

No sign of spill at the location other than impacted soil being removed.

More followup is necessary to determine if the impact area has been reseeded.

Date: 8/25/2014 Status: Inspection Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Arrived on location 8/25/2014.

Area is recovering from spill, and area has been reseeded.

No more followup is necessary.